Abstract

The monument known as "Sheikh-Kale-Parideh" set at South of the village Chahak (Herat) in parts of Khatam city in Yazd province in an obsolete cemetery.

The monument with a square plan with four arch dome style that the dome has collapsed now.

There are two cause for name of this monument among the public probability, the first reputation due to the cutting head Sheikh as founder and secondly that was due to the loss of the dome.

All of experts it belong to the era of "Ilkhanian" for the materials, design and architecture.

This building has altar muddy decoration, muddy Muqarnas in the south eastern side walls and a pair of decorative muddy **Framing** as the symbolic candles on each of the internal walls.

Monument and decorate it using adobe arrangements in size $\forall \forall * \forall \forall$ cm with \circ cm thickness then the layer of thatch and Symgel plated with \circ and \forall cm thickness approximately and a thin layer of plaster. The four sides of the monument to prevent of destruction using adobe walls with dimensions $\forall \cdot \times \forall \cdot$ cm and ξ cm thickness thatch that is attached to the cover later.

Lack of protective cover on the dome and decorative, over time, many factors such as environmental changes and atmospheric moisture and human factors, a lot of damage to the structure and decoration (such as cracks, detachment, sloughing, erosion, etc.) into come.

Since many parts of the dome collapsed, Interior monument located at against of erosion and destruction and so with the coming of winter (rainfall and snow) in the area before any further actions should be on the monument protective cover placed. Therefore, we have the best cover for the tomb of cotton fabrics due to lack or remove of moisture penetration into the tomb, but after the end of the winter season and precipitation we must proceed to the installation of cover fixed roof with extensional fabrics and metal.

Other measures, fencing, forming outpost, cutting, install gutters, drainage, humidity control, restoration and reconstruct of the damaged sections cover with thatch and Symgel.

Muddy decoration, Sheikh-Kale-Parideh monument, Yazd, restoration.